

2023 Dearborn County ADA Self - Survey

SYSTEM	CORRECTION	DISTRESS	QTY	EST COST	COMMENTS	URGENCY LEVEL 1 - 2 - 3
GOVERNMENT CENTER						
Administration Area (Gov't Ctr)						
Counters	Counters are 42" Bldg dept, Recorder, Receptionist, Auditor, Treasurer, Assessor, Health, P&Z. Should be 28-34" or service counters 36"	Inadequate	8	\$100.00	Remedy - providing clipboards and training employees to recognize when to supply them to those with ADA needs.	2
Doors/signage	18" clearance needed on latch side of door. Bldg, mtg rm(2 doors), Surveyor(pole in way).	Inadequate	4	Not feasible	Remedy - relocated signage	2
Pay Phone	Needs to be Hearing Aid compatible, Height is 55",should be 54", Protrudes more than 4" into path, needs cane detection	Inadequate	1	\$0.00	Payphones are scheduled to be removed by Combined Public Communications	3
Annex Area - Gov't Ctr						
New build completed 2018 - built to ADA standards						
Historical Courthouse (Gov't Ctr)						
Doors	Lever handles not installed at many of the doors in the historic courthouse.	Missing	21	Historical	These were not changed as to not alter the historic value of the structure. Doors are left opened during business hours and ONLY closed/opened by employees.	N/A
Doors	Path of egress swing is inadequate at a few of the doors in the historic courthouse.	Inadequate	4	Historical	These were not changed as to not alter the historic value of the structure. Doors are left opened during business hours and ONLY closed/opened by employees.	N/A
Counters	Circuit Court counters are 41-42". Service counter heights should be 36"H.	Inadequate	1	\$100.00	Remedy - providing clipboards and training employees to recognize when to supply them to those with ADA needs.	2

Tables	Table in Circuit Court, Sup Court and Juvenile are 24 3/4 - 25 3/4 " Knee clearance should be 28"-34"	Inadequate	3	\$200.00	Remedy - add lift costers to tables with instruction to staff not to remove and reason for installation	2
Pay Phone	Needs to be Hearing Aid compatible, Height is 55", should be 54", Protrudes more than 4" into path, needs cane detection	Inadequate	1	\$0.00	Payphones are scheduled to be removed by Combined Public Communications	3
	<u>JUVENILE CENTER</u>					
	NO Inadequacies					
	<u>LAW ENFORCEMENT CTR</u>					
Doors/Signage	Need 18" clearance on pull side of doors, we have 13"	Inadequate	?	Infeasible	Signage, if needed was placed in prominent area	Infeasible
Counters	Service counter height is 47 3/4" should be 36"	Inadequate	1	\$100.00	Remedy - providing clipboards and training employees to recognize when to supply them to those with ADA needs.	2
Pay Phone	Needs to be hearing aid compatible.	Inadequate	?	\$0.00	Payphones are scheduled to be removed by Combined Public Communications	3
Drinking Fountains	Needs cane detection	Inadequate	1	\$300.00	Maintenance will order and install cane bump	2
	<u>EMERGENCY MGMT AGENCY</u>					
Entrance	Needs 18" of clearance on pull side of door	Inadequate	1	Infeasible?	Signage placed in pronminent area	3
	<u>COURT SERVICES</u>					
	Probation / Community Corrections					
	NO Inadequacies					
	<u>ANIMAL CONTROL</u>					
	NO Inadequacies					

	<u>HIGHWAY DEPARTMENT</u>					
Tables	Knee space is 25.5 needs to be 27	Inadequate	1	\$200.00	Remedy - add lift costers to tables with instruction to staff not to remove and reason for installation	3
	Highway Sidewalk and Curb Ramp List					
	Per County Engineer all sidewalk and curb ramps have been bourgh to ADA compliance					
	COST: Counters/Tables			\$1,000.00		